Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

AT234 CONEY ISLAND AQUARIUM NY Spills S102446628
SSE W 8TH ST/BROARDWALK N/A

1/4-1/2 BROOKLYN, NY

0.352 mi.

1860 ft. Site 5 of 10 in cluster AT

 Relative:
 SPILLS:

 Higher
 Name:
 CONEY ISLAND AQUARIUM

 Actual:
 Address:
 W 8TH ST/BROARDWALK

3 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 9610452 / 1998-08-17

9610452 Facility ID: Facility Type: ER DER Facility ID: 206022 251359 Site ID: DEC Region: 2 Spill Cause: Unknown Spill Class: В3 SWIS: 2401 Spill Date: 1996-11-20 Investigator: **JAKOLLEE** Referred To: Not reported Reported to Dept: 1996-11-20 CID: 252

Water Affected: Not reported Spill Source: Commercial/Industrial

Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0 Date Entered In Computer: 1996-11-20

Spill Record Last Update: 2003-11-17
Spiller Name: JOHN KIRBY

Spiller Company: CONEY ISLAND AQUARIUM Spiller Address: W 8TH ST/BROARDWALK

Spiller Company: 001

Contact Name: JOHN KIRBY

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

KOLLEENY SITE INVESTIGATION PERFORMED BY LEVINE-FRICKE-RECON

INDICATED NO SIGNIFICANT IMPACTS TO SOIL OR GROUNDWATER. JK APPROVED

NO FURTHER ACTION."

Remarks: "SPILL IN PARKING LOT OF CONEY ISLAND AQUARIUM-INVESTIGATION IS GOING

ON AT THIS TIME FOR REMEDIATION"

All Materials:

251359 Site ID: Operable Unit ID: 1041961 Operable Unit: 01 Material ID: 342665 Material Code: 0009 Material Name: gasoline Case No.: Not reported Petroleum Material FA: Quantity: .00 Units: G Recovered: .00

Oxygenate: Not reported